

Appendix B.
Photographs

Appendix B. Photographs

Contents

Photos	Section.....	Page
01 – 17	Cell Excavation	B-1
18 – 64	RRM.....	B-10
65 – 72	Interim Cover	B-34
73 – 80	Spoils Embankment	B-38

Appendix B. Photographs – Cell Excavation



Photo 1. Phase 3 Cell Excavation October 2020



Photo 2. Phase 3 Cell Excavation October 2020

Appendix B. Photographs – Cell Excavation (*continued*)



Photo 3. Phase 3 Cell Excavation October 2020



Photo 4. Phase 3 Cell Excavation October 2020

Appendix B. Photographs – Cell Excavation (*continued*)



Photo 5. Cell Excavation November 2020



Photo 6. Cell Excavation November 2020

Appendix B. Photographs – Cell Excavation (*continued*)



Photo 7. Cell Excavation November 2020



Photo 8. Cell Excavation November 2020

Appendix B. Photographs – Cell Excavation (*continued*)



Photo 9. Cell Excavation December 2020



Photo 10. Cell Excavation December 2020

Appendix B. Photographs – Cell Excavation (*continued*)



Photo 11. Cell Excavation December 2020



Photo 12. Cell Excavation December 2020

Appendix B. Photographs – Cell Excavation (*continued*)



Photo 13. Cell Excavation January 2021



Photo 14. Cell Excavation January 2021

Appendix B. Photographs – Cell Excavation (*continued*)



Photo 15. Cell Excavation February 2021



Photo 16. Cell Excavation February 2021

Appendix B. Photographs – Cell Excavation (*continued*)



Photo 17. Completed Cell Excavation February 2021

Appendix B. Photographs – RRM



Photo 18. Dozer placing material October 2020



Photo 19. Placement of RRM October 2020

Appendix B. Photographs – RRM (continued)



Photo 20. View looking North October 2020



Photo 21. RRM Loadout November 2020

Appendix B. Photographs – RRM (continued)



Photo 22. RRM ready for placement November 2020



Photo 23. RRM placement November 2020

Appendix B. Photographs – RRM (*continued*)



Photo 24. RRM Compaction December 2020



Photo 25. Breaking up Frost December 2020

Appendix B. Photographs – RRM (continued)



Photo 26. Loading RRM December 2020



Photo 27. Placing a Debris Lift December 2020

Appendix B. Photographs – RRM (continued)



Photo 28. RRM Debris Lift December 2020



Photo 29. Material being placed December 2020

Appendix B. Photographs – RRM (*continued*)



Photo 30. Lift Prepared for In-place Density Test January 2021



Photo 31. Snow and Frost Removal January 2021

Appendix B. Photographs – RRM (*continued*)



Photo 32. Equipment Placing RRM January 2021

Appendix B. Photographs – RRM (*continued*)



Photo 33. Cell Operations February 2021



Photo 34. Pushing Soils While Snowing February 2021

Appendix B. Photographs – RRM (continued)



Photo 35. Soils Placement February 2021



Photo 36. RRM Lift February 2021

Appendix B. Photographs – RRM (*continued*)



Photo 37. Aerial Picture of Disposal Cell March 2021



Photo 38. Debris Being Covered March 2021

Appendix B. Photographs – RRM (continued)



Photo 39. RRM Loadout March 2021



Photo 40. RRM Lifts March 2021

Appendix B. Photographs – RRM (continued)



Photo 41. Hauling RRM for Placement April 2021



Photo 42. RRM Loadout April 2021

Appendix B. Photographs – RRM (continued)



Photo 43. Loader Loading Material in Haul Truck April 2021



Photo 44. Equipment Placing RRM Material on Lift Area April 2021

Appendix B. Photographs – RRM (continued)



Photo 45. Aerial Photo of RRM being Placed May 2021



Photo 46. RRM Placement May 2021

Appendix B. Photographs – RRM (continued)



Photo 47. Placement of Material on Lift Area by Haul Truck May 2021



Photo 48. Preparing for Sand Cone Testing May 2021

Appendix B. Photographs – RRM (continued)



Photo 49. Placing RRM June 2021



Photo 50. Dozer Placing RRM on Active Lift Area June 2021

Appendix B. Photographs – RRM (continued)



Photo 51. Haul Truck Dumping RRM of Lift Area June 2021



Photo 52. Watering Area for Dust Control June 2021

Appendix B. Photographs – RRM (continued)



Photo 53. Multiple Disposal Cell Operations July 2021



Photo 54. Hauling RRM for Placement July 2021

Appendix B. Photographs – RRM (continued)



Photo 55. Equipment Preparing RRM Lift July 2021



Photo 56. Dozer used for RRM Lifts July 2021

Appendix B. Photographs – RRM (continued)



Photo 57. Compaction of 4th RRM Lift in Top 7 Feet August 2021



Photo 58. RRM Placement August 2021

Appendix B. Photographs – RRM (continued)



Photo 59. Dozer Pushing Material on RRM Lift August 2021



Photo 60. Looking South at the Disposal Cell August 2021

Appendix B. Photographs – RRM (*continued*)



Photo 61. Placement of Debris Lift September 2021



Photo 62. Dust Suppression and Moisture Conditioning September 2021

Appendix B. Photographs – RRM (continued)



Photo 63. Pushing and Dumping RRM September 2021



Photo 64. Pushing RRM September 2021

Appendix B. Photographs – Interim



Photo 65. Aerial of Ongoing Interim May 2021



Photo 66. Aerial of Interim Placement May 2021

Appendix B. Photographs – Interim (*continued*)



Photo 67. Pushing Interim May 2021



Photo 68. Pushing Out of the Stock Pile May 2021

Appendix B. Photographs – Interim (*continued*)



Photo 69. Interim Loadout June 2021



Photo 70. Interim Protective Cover Haul June 2021

Appendix B. Photographs – Interim (*continued*)



Photo 71. Dozer Pushing Interim Cover Material June 2021



Photo 72. North Side Interim June 2021

Appendix B. Photographs – Spoils Embankment



Photo 73. Constructing Spoils Embankment October 2020



Photo 74. Placing Spoils Embankment Lift October 2020

Appendix B. Photographs – Spoils Embankment (*continued*)



Photo 75. Spoils Embankment Construction October 2020



Photo 76. Hauling Material for Placement on Spoils Embankment November 2020

Appendix B. Photographs – Spoils Embankment (*continued*)



Photo 77. Constructing Spoils Embankment November 2020



Photo 78. Transporting Material to Spoils Embankment December 2020

Appendix B. Photographs – Spoils Embankment (*continued*)



Photo 79. Transporting Material to Spoils Embankment January 2021



Photo 80. Scraper Hauling Spoils Embankment Material January 2021