

**Appendix B.  
Photographs**

**Crescent Junction Disposal Cell Completion Report Addendum E  
Appendix B. Photographs**

**Contents**

Photos	Section	Page
01-05.	<b>Perimeter Embankment</b> .....	<b>B-1</b>
06-31.	<b>RRM</b> .....	<b>B-4</b>
32.	<b>Infiltration and Biointrusion Barrier</b> .....	<b>B-17</b>
33-35.	<b>Frost Protection Layer</b> .....	<b>B-18</b>

## Appendix B. Photographs – Perimeter Embankment



*Photo 1. Preparing Material for Perimeter Embankment September 9, 2015*



*Photo 2. Dump Ramp Removal September 9, 2015*

**Appendix B. Photographs – Perimeter Embankment (*continued*)**



*Photo 3. Embankment Construction September 28, 2015*



*Photo 4. QC Embankment Inspection September 9, 2015*

**Appendix B. Photographs – Perimeter Embankment (*continued*)**



*Photo 5. Compaction and Moisture Conditioning of Embankment Fill September 10, 2015*

## Appendix B. Photographs – RRM



*Photo 6. RRM Placement October 17, 2014*



*Photo 7. Modified Container Dumping November 6, 2014*

**Appendix B. Photographs – RRM (continued)**



*Photo 8. Modified Container Dumping November 6, 2014*



*Photo 9. RRM Placement December 29, 2014*

**Appendix B. Photographs – RRM (continued)**



*Photo 10. RRM Placement December 29, 2014*



*Photo 11. RRM Placement December 29, 2014*



**Appendix B. Photographs – RRM (continued)**



*Photo 12. RRM Placement January 8, 2015*



*Photo 13. RRM Placement January 16, 2015*

**Appendix B. Photographs – RRM (continued)**



*Photo 14. RRM Placement March 11, 2015*



*Photo 15. RRM Placement March 11, 2015*

**Appendix B. Photographs – RRM (continued)**



*Photo 16. RRM Placement March 11, 2015*



*Photo 17. Dust Control March 11, 2015*

**Appendix B. Photographs – RRM (continued)**



*Photo 18. RRM Placement April 15, 2015*



*Photo 19. RRM Compaction April 15, 2015*

**Appendix B. Photographs – RRM (continued)**



*Photo 20. RRM Compaction April 28, 2015*



*Photo 21. RRM Placement April 28, 2015*

**Appendix B. Photographs – RRM (continued)**



*Photo 22. RRM Compaction June 23, 2015*



*Photo 23. RRM Placement June 23, 2015*

**Appendix B. Photographs – RRM (continued)**



*Photo 24. RRM Compaction June 23, 2015*



*Photo 25. RRM Placement July 1, 2015*

**Appendix B. Photographs – RRM (continued)**



*Photo 26. RRM Placement July 1, 2015*



*Photo 27. RRM Placement July 22, 2015*



**Appendix B. Photographs – RRM (continued)**



*Photo 28. RRM Placement July 29, 2015*



*Photo 29. RRM Placement August 25, 2015*

**Appendix B. Photographs – RRM (continued)**



*Photo 30. RRM Placement August 25, 2015*



*Photo 31. RRM Conditioning September 18, 2015*

## Appendix B. Photographs – Infiltration and Biointrusion Barrier



*Photo 32. Biointrusion Barrier Sampling October 9, 2014*

## Appendix B. Photographs – Frost Protection Layer



*Photo 33. Frost Protection Layer Placement October 14, 2014*



*Photo 34. Frost Protection Layer Placement October 14, 2014*

**Appendix B. Photographs – Frost Protection Layer (*continued*)**



*Photo 35. Frost Protection Layer Placement October 29, 2014*