

Appendix B.
Photographs

**Crescent Junction Disposal Cell Completion Report Addendum D
Appendix B. Photographs**

Contents

Photos	Section	Page
01 – 23	RRM Placement.....	B-1
24 – 28	Interim Cover.....	B-13
29 – 36	Radon Barrier	B-16
37 – 42	Infiltration and Biointrusion Barrier.....	B-20
43 – 48	Frost Protection Layer	B-23

RRM



Photo 1. RRM Placement October 21, 2013



Photo 2. RRM Placement October 28, 2013

RRM (continued)



Photo 3. RRM Placement October 28, 2013



Photo 4. RRM Placement October 28, 2013

RRM (continued)



Photo 5. RRM Placement November 12, 2013



Photo 6. RRM Placement November 12, 2013

RRM (continued)



Photo 7. RRM Placement November 14, 2013



Photo 8. RRM Placement December 17, 2013

RRM (continued)



Photo 9. RRM Placement December 17, 2013



Photo 10. RRM Placement January 7, 2014

RRM (continued)



Photo 11. RRM Placement January 17, 2014



Photo 12. RRM Placement February 11, 2014

RRM (continued)



Photo 13. RRM Placement February 11, 2014



Photo 14. RRM Placement March 4, 2014

RRM (continued)



Photo 15. RRM Placement March 4, 2014



Photo 16. RRM Placement April 1, 2014

RRM (continued)



Photo 17. RRM Placement April 22, 2014



Photo 18. RRM Placement April 23, 2014

RRM (continued)



Photo 19. RRM Placement May 1, 2014



Photo 20. RRM Placement May 6, 2014

RRM (continued)



Photo 21. RRM Placement June 5, 2014



Photo 22. RRM Placement June 26, 2014

RRM (continued)



Photo 23. RRM Placement July 31, 2014

Interim Cover



Photo 24. Interim Cover July 31, 2014



Photo 25. Interim Cover July 31, 2014

Interim Cover (continued)



Photo 26. Interim Cover July 31, 2014



Photo 27. Interim Cover July 31, 2014

Interim Cover (continued)



Photo 28. Interim Cover August 12, 2014

Radon Barrier



Photo 29. Radon Barrier August 2014



Photo 30. Radon Barrier August 2014

Radon Barrier (continued)



Photo 31. Radon Barrier September 10, 2014



Photo 32. Radon Barrier September 10, 2014

Radon Barrier (continued)



Photo 33. Radon Barrier September 18, 2014



Photo 34. Radon Barrier September 18, 2014

Radon Barrier (continued)



Photo 35. Radon Barrier September 23, 2014



Photo 36. Radon Barrier September 26, 2014

Infiltration and Biointrusion Barrier



Photo 37. Infiltration and Biointrusion Barrier September 13, 2014



Photo 38. Infiltration and Biointrusion Barrier September 16, 2014

Infiltration and Biointrusion Barrier (continued)



Photo 39. Infiltration and Biointrusion Barrier September 16, 2014



Photo 40. Infiltration and Biointrusion Barrier September 16, 2014

Infiltration and Biointrusion Barrier (*continued*)



Photo 41. Infiltration and Biointrusion Barrier September 16, 2014



Photo 42. Infiltration and Biointrusion Barrier September 16, 2014

Frost Protection Layer



Photo 43. Frost Protection Layer September 19, 2014



Photo 44. Frost Protection Layer September 19, 2014

Frost Protection Layer (continued)



Photo 45. Frost Protection Layer September 19, 2014



Photo 46. Frost Protection Layer September 25, 2014

Frost Protection Layer (continued)



Photo 47. Frost Protection Layer September 25, 2014



Photo 48. Frost Protection Layer September 25, 2014