

**Appendix B.**  
**Photographs**

# Appendix B. Photographs

## Contents

Photo	Section	Page
01-07.	Cell Excavation.....	B-1
08-10.	Perimeter Embankment.....	B-5
11-30.	RRM.....	B-7
31-32.	Interim Cover.....	B-17
33-35.	Spoils Embankment.....	B-18

## Appendix B. Photographs – Cell Excavation



*Photo 1. Removal of Former Dump Ramp in Phase 2 October 1, 2015*



*Photo 2. Removal of Former Dump Ramp in Phase 2 October 1, 2015*

**Appendix B. Photographs – Cell Excavation (*continued*)**



*Photo 3. Phase 3a Cell Excavation March 22, 2016*



*Photo 4. Phase 3a Cell Excavation April 5, 2016*

**Appendix B. Photographs – Cell Excavation (*continued*)**



*Photo 5. Phase 3a Cell Excavation April 7, 2016*



*Photo 6. Phase 3a Cell Excavation April 18, 2016*

**Appendix B. Photographs – Cell Excavation (*continued*)**




*Photo 7. Phase 3a Cell Excavation May 12, 2016*

## Appendix B. Photographs – Perimeter Embankment



*Photo 8. Perimeter Embankment October 8, 2015*



*Photo 9. Perimeter Embankment October 2015*

**Appendix B. Photographs – Perimeter Embankment (*continued*)**



*Photo 10. Perimeter Embankment October 2015*



## Appendix B. Photographs – RRM



*Photo 11. RRM Placement October 26, 2015*



*Photo 12. RRM Placement November 17, 2015*

**Appendix B. Photographs – RRM (continued)**



*Photo 13. RRM Placement December 8, 2015*



*Photo 14. RRM Placement December 10, 2015*

**Appendix B. Photographs – RRM (continued)**




*Photo 15. RRM Placement January 28, 2016*



*Photo 16. RRM Placement February 4, 2016*

**Appendix B. Photographs – RRM (continued)**



*Photo 17. Compaction of RRM Placement near Standpipe 01, February 26, 2016*



*Photo 18. RRM Placement March 29, 2016*

**Appendix B. Photographs – RRM (continued)**



*Photo 19. RRM Placement April 13, 2016*



*Photo 20. RRM Placement May 26, 2016*

**Appendix B. Photographs – RRM (continued)**



*Photo 21. RRM Placement June 8, 2016*



*Photo 22. RRM Placement June 8, 2016*

## Appendix B. Photographs – RRM (continued)



*Photo 23. RRM Placement - Standpipe Compaction June 20, 2016*



*Photo 24. RRM Placement - Standpipe Compaction July 5, 2016*

## Appendix B. Photographs – RRM (continued)



*Photo 25. RRM Placement Top of Waste July 26, 2016*



*Photo 26. RRM Placement Top of Waste August 4, 2016*



**Appendix B. Photographs – RRM (continued)**



*Photo 27. RRM Placement August 9, 2016*



*Photo 28. RRM Placement - Debris August 23, 2016*

**Appendix B. Photographs – RRM (continued)**



*Photo 29. RRM Placement September 8, 2016*



*Photo 30. RRM Placement September 8, 2016*

## Appendix B. Photographs – Interim Cover



*Photo 31. Interim Cover Placement August 25, 2016*



*Photo 32. Completed Interim Cover September 8, 2016*

## Appendix B. Photographs – Spoils Embankment



*Photo 33. Spoils Embankment Placement April 5, 2016*



*Photo 34. Spoils Embankment Placement April 5, 2016*

**Appendix B. Photographs – Spoils Embankment (*continued*)**



*Photo 35. Spoils Embankment Placement May 12, 2016*