

**Appendix B.**  
**Photographs**

# Appendix B. Photographs

## Contents

Photo	Section	Page
<b>01-08.</b>	<b>Cell Excavation .....</b>	<b>B-1</b>
<b>09-28.</b>	<b>RRM.....</b>	<b>B-5</b>
<b>29-31.</b>	<b>Spoils Embankment.....</b>	<b>B-15</b>

## Appendix B. Photographs – Cell Excavation



*Photo 1. Phase 3b Cell Excavation March 21, 2017*



*Photo 2. Phase 3b Cell Excavation March 21, 2017*

**Appendix B. Photographs – Cell Excavation (*continued*)**



*Photo 3. Phase 3b Cell Excavation March 22, 2017*



*Photo 4. Phase 3b Cell Excavation April 7, 2017*

**Appendix B. Photographs – Cell Excavation (*continued*)**



*Photo 5. Phase 3b Cell Excavation April 20, 2017*



*Photo 6. Phase 3b Cell Excavation April 20, 2017*

**Appendix B. Photographs – Cell Excavation (*continued*)**



*Photo 7. Phase 3b Cell Excavation May 15, 2017*



*Photo 8. Phase 3b Cell Excavation May 15, 2017*

## Appendix B. Photographs – RRM



*Photo 9. RRM Placement October 11, 2016*




*Photo 10. RRM Placement – Standpipe Compaction November 8, 2016*

**Appendix B. Photographs – RRM (continued)**



*Photo 11. RRM Placement December 28, 2016*



*Photo 12. Nuclear Density Gauge Testing January 4, 2017*



**Appendix B. Photographs – RRM (continued)**



*Photo 13. RRM Placement February 7, 2017*



*Photo 14. RRM Placement February 9, 2017*

**Appendix B. Photographs – RRM (continued)**



*Photo 15. RRM Placement February 9, 2017*



*Photo 16. RRM Placement March 21, 2017*

**Appendix B. Photographs – RRM (continued)**



*Photo 17. Compaction of RRM Placement near Standpipe 01, April 20, 2017*



*Photo 18. RRM Placement May 24, 2017*

**Appendix B. Photographs – RRM (continued)**



*Photo 19. RRM Placement June 1, 2017*



*Photo 20. RRM Loadout June 27, 2017*

**Appendix B. Photographs – RRM (continued)**



*Photo 21. RRM Moisture Conditioning June 27, 2017*



*Photo 22. RRM Placement July 27, 2017*

## Appendix B. Photographs – RRM (continued)



Photo 23. RRM Placement August 1, 2017



Photo 24. Container Dumping August 29, 2017

**Appendix B. Photographs – RRM (continued)**



*Photo 25. RRM Placement August 29, 2017*



*Photo 26. RRM Placement August 29, 2017*

**Appendix B. Photographs – RRM (continued)**



*Photo 27. RRM Loadout September 5, 2017*



*Photo 28. RRM Placement September 12, 2017*



## Appendix B. Photographs – Spoils Embankment



*Photo 29. Spoils Embankment Placement March 21, 2017*



*Photo 30. Spoils Embankment Placement April 20, 2017*

**Appendix B. Photographs – Spoils Embankment (*continued*)**



*Photo 31. Spoils Embankment May 25, 2017*