

CJ Interim Completion Report – Addendum L

**Appendix B.
Photographs**

Appendix B. Photographs

Contents

Photos	Section	Page
1 - 72	RRM.....	B-1
73 - 78	Interim Cover	B-36

Appendix B. Photographs – RRM



Photo 1. Pushing RRM October 2021



Photo 2. Compacting RRM October 2021

Appendix B. Photographs – RRM (continued)



Photo 3. Dozer Keying in RRM Lift October 2021



Photo 4. Stock Piling RRM October 2021

Appendix B. Photographs – RRM (continued)



Photo 5. Cell Floor by Water Loadout October 2021



Photo 6. Pushing RRM on RRM Lift October 2021

Appendix B. Photographs – RRM (continued)



Photo 7. Placing RRM November 2021



Photo 8. Placing and Pushing RRM November 2021

Appendix B. Photographs – RRM (continued)



Photo 9. Pushing RRM November 2021



Photo 10. Preparing for Moisture Density Test November 2021

Appendix B. Photographs – RRM (*continued*)



Photo 11. Moisture Conditioning RRM November 2021



Photo 12. Moisture Density Testing November 2021

Appendix B. Photographs – RRM (continued)



Photo 13. Pushing RRM December 2021



Photo 14. Sand Cone Compaction Testing December 2021

Appendix B. Photographs – RRM (continued)



Photo 15. Sand Cone Testing December 2021



Photo 16. Pushing RRM December 2021

Appendix B. Photographs – RRM (continued)



Photo 17. RRM Ready to be Placed December 2021



Photo 18. Spoils Stockpile Hauling to North side of Cell December 2021

Appendix B. Photographs – RRM (continued)



Photo 19. Sacrificial 2" RRM Lift January 2022



Photo 20. Placing RRM in Top Seven Feet January 2022

Appendix B. Photographs – RRM (continued)



Photo 21. Farming RRM January 2022



Photo 22. Transporting RRM January 2022

Appendix B. Photographs – RRM (continued)



Photo 23. RadCon performing 707pCi/g Analysis January 2022



Photo 24. Active Lifts Map January 2022

Appendix B. Photographs – RRM (continued)



Photo 25. Pushing RRM February 2022



Photo 26. Snow Removal on RRM Lift February 2022

Appendix B. Photographs – RRM (continued)



Photo 27. Placing RRM February 2022



Photo 28. Snow Removal February 2022

Appendix B. Photographs – RRM (continued)



Photo 29. Snow Removal February 2022



Photo 30. Hauling RRM February 2022

Appendix B. Photographs – RRM (continued)



Photo 31. Sand Cone Testing March 2022



Photo 32. Disposal Cell Operations March 2022

Appendix B. Photographs – RRM (continued)



Photo 33. 707pCi/g Sampling March 2022



Photo 34. Placing RRM March 2022

Appendix B. Photographs – RRM (continued)



Photo 35. Working RRM Lift March 2022



Photo 36. Decon Operations March 2022

Appendix B. Photographs – RRM (*continued*)



Photo 37. Water Truck on RRM Lift April 2022



Photo 38. Moisture Conditioning RRM April 2022

Appendix B. Photographs – RRM (continued)



Photo 39. Troxler Testing for Compaction April 2022



Photo 40. RRM Placement April 2022

Appendix B. Photographs – RRM (continued)



Photo 41. Pushing RRM on Lift April 2022



Photo 42. Dumping RRM on Lift April 2022

Appendix B. Photographs – RRM (continued)



Photo 43. Dozer Waiting for RRM May 2022



Photo 44. Moisture Conditioning and Compacting RRM Lift May 2022

Appendix B. Photographs – RRM (*continued*)



Photo 45. Dozer Pushing Load from Artic Truck May 2022



Photo 46 Top of Waste Lift May 2022

Appendix B. Photographs – RRM (continued)



Photo 47. Early Morning Fuel Up May 2022



Photo 48. Dozer Climbing up to Lift May 2022

Appendix B. Photographs – RRM (continued)



Photo 49. 707pCi/g Sampling on Lift June 2022



Photo 50. Pushing and Compacting RRM Lift June 2022

Appendix B. Photographs – RRM (continued)



Photo 51. Placing RRM Lift June 2022



Photo 52 . Moisture Conditioning and Dust Suppression June 2022

Appendix B. Photographs – RRM (continued)



Photo 53 Compacting Lift June 2022



Photo 54. Pushing on RRM Lift June 2022

Appendix B. Photographs – RRM (continued)



Photo 55. Compacting Looking South July 2022



Photo 56. Compacting Looking East July 2022

Appendix B. Photographs – RRM (continued)



Photo 57. Pushing Stockpile onto RRM Lift July 2022



Photo 58. Dumping RRM on Lift July 2022

Appendix B. Photographs – RRM (continued)



Photo 59. Dozer Cleaning up Stockpile Looking East July 2022



Photo 60. Cleaning up Stockpile July 2022

Appendix B. Photographs – RRM (continued)



Photo 61. Grading Top of Waste August 2022



Photo 62. TOW Verification August 2022

Appendix B. Photographs – RRM (continued)



Photo 63. One Point Proctor Prep August 2022



Photo 64. Grading TOW August 2022

Appendix B. Photographs – RRM (continued)



Photo 65. Grading TOW August 2022



Photo 66. Graded TOW August 2022

Appendix B. Photographs – RRM (*continued*)



Photo 67. Storm Coming In September 2022



Photo 68. Stockpiling September 2022

Appendix B. Photographs – RRM (continued)



Photo 69 Transporting RRM September 2022



Photo 70. Dust Control September 2022

Appendix B. Photographs – RRM (*continued*)



Photo 71. Antelope Crossing Disposal Cell September 2022



Photo 72. Moisture Conditioning Lifts September 2022

Appendix B. Photographs – Interim Cover



Photo 73. Pushing Interim Lift Looking Southwest November 2021



Photo 74. Spoils Pile Material for Interim Lift November 2021

Appendix B. Photographs – Interim Cover (continued)



Photo 75. Interim Cover Looking Southwest November 2021



Photo 76. Interim Cover Looking Southwest November 2021

Appendix B. Photographs – Interim Cover (continued)



Photo 77. Interim Cover Looking Southeast November 2021



Photo 78. Surveying Top of Interim Cover December 2021